



Australian
National
University

ANU HIAF 14UD


High Voltage Performance Degradation of the 14UD Tandem Accelerator

Linardakis P., Lobanov N., Tunningley T., Tsifakis T., Battisson S., Graham B., Bockwinkel J., Heighway J.
HIAT 2018 – Lanzhou, China



Australian
National
University


ANU HIAF 14UD





Australian
National
University

ANU HIAF 14UD






Australian
National
University

ANU HIAF 14UD

- 1971: pressure vessel complete
- 1972: 14UD assembly began
- 1973: first beam
- 1974: first experiment
- 1975: acceptance tests complete





Australian
National
University

14UD voltage records

- Conditioned to 14.8MV in 1983 (with corona points)
- Upgrade to “compressed geometry” and resistors in ~1990
 - Conditioned to 16.7 MV
 - Experiments at 15.5 MV
- Now at 14.5 MV max for experiments






14UD voltage records

Since January 2016:



- Running for 56% of the total time
- Accelerator downtime for maintenance for 16% of the total time (both scheduled and unscheduled)
- Above 13.5 MV for 27% of time with terminal volts.





Australian
National
University



Voltage breakdown





Australian
National
University



Voltage breakdown





SF₆ breakdown

- $\text{SF}_6 \rightarrow \text{SF}_4 + 2\text{F}$
- $\text{SF}_4 + \text{H}_2\text{O} \rightarrow \text{SOF}_2 + 2\text{HF}$
- $\text{SOF}_2 + \text{H}_2\text{O} \rightarrow \text{SO}_2 + 2\text{HF}$
- $2\text{F} + \text{M} \rightarrow \text{MF}_n$ (where M is any metal)





Australian
National
University


SF₆ breakdown






Vacuum breakdown

- Vacuum breakdown triggers:
 - field emission from protrusions on electrode surfaces, either from manufacture or previous discharges;
 - field emission from foreign particulates embedded in the electrode surfaces;
 - ionisation of gas or other low vapour pressure contaminants desorbed from electrode surfaces that then cause micro-discharges;
 - hot field emission from impacting particles that deform the electrodes and;
 - ionisation of metal vapour from high-energy particle impact.



Vacuum breakdown


- Vacuum breakdown triggers:
 - field emission from protrusions on electrode surfaces, either from manufacture or previous discharges;
 - field emission from foreign particulates embedded in the electrode surfaces;
 - ionisation of gas or other low vapour pressure contaminants desorbed from electrode surfaces that then cause micro-discharges;
 - hot field emission from impacting particles that deform the electrodes and;
 - ionisation of metal vapour from high-energy particle impact.






Vacuum arcs

- Electrode surface conditioning
- In-situ cycling of terminal voltage with a gradual increase over time
- Vacuum and x-ray emission used to guide level of conditioning




SF₆ ingress into vacuum





SF₆ ingress into vacuum


- RGA search for SF₆
 - Sudden leak while idle





SF₆ ingress into vacuum


- RGA search for SF₆
 - Small “burps” while pumping SF₆ from pressure vessel





Australian
National
University



Ceramic insulators





Australian
National
University



Ceramic insulators





Australian
National
University


Ceramic insulators





Australian
National
University


Ceramic insulators





Australian
National
University


Ceramic insulators





Australian
National
University



Ceramic insulators





Australian
National
University

Ceramic insulators




Damage arising from
aluminum bonding
layer between titanium
and ceramic



Australian
National
University


Electrode surface condition





Australian
National
University

Electrode surface condition





Australian
National
University

Electrode surface condition

HIGHEST


MIDPOINT

LOWEST

TOP SURFACE




BOTTOM SURFACE







Australian
National
University


Electrode surface condition




Porosity




Recrystallization




Unused Ti




Metal vaporisation



Layer build-up




Melting




Electrode edge



Electrode surface condition



HV	det	mode	dwell	curr	WD	mag	HFV	tilt	4 μm
10.00 kV	MD	None	1 μs	1.6 nA	9.1 mm	12 000 x	17.3 μm	0 °	Verios




HV	det	mode	dwell	curr	WD	mag	HFV	tilt	1 μm
5.00 kV	TLD	SE	3 μs	0.20 nA	4.9 mm	50 000 x	4.14 μm	0 °	Verios

Porosity



Australian
National
University

Electrode surface condition






Layer build-up




Electrode surface condition

- SEM EDX on used electrodes
 - oxygen 20 – 40%
 - carbon 10 – 20%
 - **fluorine** 3 – 7%
 - aluminium 1 – 3%
- Unused Ti
 - oxygen 10 – 15%
 - carbon 3 – 6%






Electrode surface condition



- Damaged electrodes exacerbate vacuum breakdown triggers
 - Field emission from protrusions
 - Ionisation of metal vapour





Australian
National
University

Remediation

- New tubes
- Factory refurbishment (NEC)
- In-house refurbishment
 - High-pressure rinse
 - Electro-polishing



Australian
National
University

Thank you